

## IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:	)	Examiner: Fahmida Rahman
	:	
TETSUYA KAWANABE	)	Group Art Unit: 2116
	:	
Appln. No.: 10/800,662	)	Confirmation No.: 4728
	:	
Filed: March 16, 2004	)	Patent No.: US 7,424,625 B2
	:	
For: PRINTING APPARATUS AND	)	Issued: September 9, 2008
POWER SUPPLY CONTROL METHOD	:	
IN PRINTING APPARATUS	)	February 11, 2009

Commissioner for Patents  
P.O. Box 1450  
Alexandria, VA 22313-1450

REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULE 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form (PTO-1050) is enclosed.

The \$100.00 fee for the Certificate of Correction is being paid electronically. The Commissioner is authorized to charge any underpayment or credit any overpayment to Deposit Account No. 06-1205.

Patentee's undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

/Edmund J. Haughey/

---

Edmund J. Haughey  
Attorney for Patentee  
Registration No. 44,749

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3800  
Facsimile: (212) 218-2200

EJH:tayr  
28206064 v 1

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

Staple  
Here  
Only!

PRINTER'S TRIM LINE

**PATENT NO. :** US 7,424,625 B2

**DATED :** September 9, 2008

**INVENTOR(S) :** KAWANABE

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

**COLUMN 2:**

Line 31, "respectively" should read --respective--.

**COLUMN 4:**

Line 30, "and" should read --an--.

Line 50, "making" should read --making them--.

**COLUMN 6:**

Line 32, "the LED" should read --the LEDs--.

**COLUMN 10:**

Line 21, "FIG. 6." should read --to FIG. 6--.

**COLUMN 11:**

Line 41, "state S24." should read --state ST24--.

**COLUMN 12:**

Line 16, "supply  $V_{cd}$ " should read -- $V_{cd}$ --.

**MAILING ADDRESS OF SENDER:**

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3800  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

**PATENT NO. US 7,424,625 B2**

No. of add'l. copies  
@ 30¢ per page



**Form PTO 1050 (Rev. 3-82)**

EJH:ayr FCHS\_WS 2826064 v1

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

Staple  
Here  
Only!

PRINTER'S TRIM LINE

**PATENT NO. :** US 7,424,625 B2

**DATED :** September 9, 2008

**INVENTOR(S) :** KAWANABE

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

**COLUMN 13:**

Line 28, "once" should read --first--.

Line 50, "informed, or is queried," should read --informed--.

**COLUMN 15:**

Line 52, "once" should read --first--.

**MAILING ADDRESS OF SENDER:**

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3800  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

**PATENT NO. US 7,424,625 B2**

No. of add'l. copies  
@ 30¢ per page



**Form PTO 1050 (Rev. 3-82)**

EJH:ayr FCHS\_WS 2826064 v1